



**PRISM**

**SDI / IP Waveform Monitor**

**Release Notes**

This document supports firmware version 2.5

[www.telestream.net](http://www.telestream.net)

D00013695A

Copyright © 2022 Telestream, LLC and its Affiliates. All rights reserved. Telestream products are covered by U.S. and foreign patents, issued and pending. Information in this publication supersedes that in all previously published material. Specification and price change privileges reserved. TELESTREAM is a registered trademark of Telestream, LLC. All other trade names referenced are the service marks, trademarks, or registered trademarks of their respective companies.

Telestream products are covered by U.S. and foreign patents, issued and pending. Information in this publication supersedes that in all previously published material. Specifications and price change privileges reserved.

TELESTREAM is a registered trademark of Telestream, LLC.

Dolby, Dolby Audio, and the double-D symbol are trademarks of Dolby Laboratories.

**Contact Telestream**

Telestream LLC  
848 Gold Flat Road  
Nevada City, CA 95959  
USA

For product information, sales, service, and technical support:  
Worldwide, visit [www.telestream.net/telestream-support/video/support.htm](http://www.telestream.net/telestream-support/video/support.htm) to find contacts in your area.

# Release notes

This document describes new features, fixes, and improvements of firmware version 2.5 for the PRISM SDI / IP Waveform Monitor.

## Compatible Products

**Upgrades**    The following 10G products are compatible with this release:

- MPI and MPX without 25G upgrade
- MPI2-10 and MPX2-10 without 25G upgrade

---

**NOTE:** The following 25G products are not compatible with this release, and should have version 3.x or later

- MPI and MPX that have been upgraded to 25G
  - MPI2-10 and MPX2-10 that have been upgraded to 25G
  - MPI2-25 and MPX2-25
  - MPS-100/200/300
  - MPD-100/200/300
- 

## New features

- Selectable PTP or RTC time on the Status bar

## Resolved Issues and Improvements

This firmware release has the following resolved issues and improvements. Unless otherwise noted, fixes and improvements apply to all products listed in the **Compatible Products** section.

- Audio** • Fixed issue with Audio application occasionally indicating sporadic “Not Present” messages, which may be audible.
- AUX SDI Output** • Lines and double vision on SDI output
- NMOS** • Improved NMOS and API switching performance for IP inputs
- PTP** • PTP Locked green LED is not displaying
- SDI Input** • Improved SDI input performance at cable lengths between 20 – 30 meters
- SNMP** • MIB missing z character in revision date field
  - Unexpected SNMP vulnerabilities
  - PRISM SNMP Trap are not compliant with RFC 3416
- System** • Database Grows to giant size preventing software from starting
  - Stability improvements