**telestream**

**PRISM**

**SDI / IP Waveform Monitor**

**Release Notes**

**Contact Telestream**
Telestream LLC
848 Gold Flat Road
Nevada City, CA 95959
USA

For product information, sales, service, and technical support:
Worldwide, visit www.telestream.net/telestream-support/video/support.htm to find contacts in your area.

# Release notes

This document describes new features, fixes, and improvements of firmware version 3.3.2 for the PRISM SDI / IP Waveform Monitor.

**NOTE:** This document contains detailed information about PRISM product software and hardware defects. It is for use by Telestream personnel only.

## Compatible Products

**Upgrades**    The following 25G products are compatible with this release:

- MPI and MPX that have been upgraded to 25G

- MPI2-10 and MPX2-10 that have been upgraded to 25G

- MPI2-25 and MPX2-25

- MPS-100/200/300

- MPD-100/200/300

**NOTE**: V3.3.x is not compatible with:

- MPI and MPX without 25G upgrade

- MPI2-10 and MPX2-10 without 25G upgrade

**Downgrades**    Downgrading from version 3.x to 2.x is not allowed for the following products due to the hardware configuration:

- MPI2-25 with serial number starting at S010564

- MPX2-25 with serial number starting at S010386

- All MPS/MPD products

## New features

- Persistent NMOS Receiver with user configurable target input. (Refer to the v3.3.2 User Manual for details)

## Resolved Issues and Improvements

This firmware release has the following resolved issues and improvements. Unless otherwise noted, fixes and improvements apply to all products listed in the **Compatible Products** section.

**Boot**
- Touch panel, front panel and/or UI are sometimes not initialized properly in system boot up

**Eye Pattern**
- Eye pattern sometimes is not initialized properly

**NMOS**
- Responding HTTP 308 instead of HTTP 301 when wrong URL address is given
- Session attribute in SDP file causes failed NMOS activations

**Settings Input Menu**
- Format selection sometimes automatically returns to "Auto" when a parameter is manually selected
- Scrolling menu sometimes unexpectedly closes the drop-down list